

CERTIFIED MAIL #7012 1640 0000 0213 7165 RETURN RECEIPT REQUESTED

STATE OF TENNESSEE TENNESSEE DEPARTMENT OF ENVIRONMENT AND CONSERVATION JOHNSON CITY ENVIRONMENTAL FIELD OFFICE

2305 SILVERDALE ROAD
JOHNSON CITY, TENNESSEE 37601-2162
STATFWIDE 1-888-891-8332 FAX (423) 854-5401

April 10, 2013

Ms. Victoria S. Conley Corporate Environmental Manager AGC Glass Company North America 1400 Lincoln Street Kingsport, TN 37660

RE: Compliance Evaluation Inspection

(423) 854-5400

AGC Flat Glass North America, Inc. – Kingsport Plant

NPDES Permit TN0003905

Sullivan County

Dear Ms. Conley:

Tennessee Department of Environment and Conservation, Division of Water Resources personnel performed a planned inspection at AGC Flat Glass North America, Inc. – Kingsport Plant on March 28, 2013. The division thanks AGC personnel for their assistance during this inspection. Inspection observations are detailed below. Also see the enclosed Water Compliance Inspection Report for further detail.

The inspection revealed that facility operations have ceased as previously reported in local media and on monthly Discharge Monitoring Reports (DMRs) submitted to the division. Shipment of finished glass from the site continues, but, in general, the facility assets are currently frozen pending sale of the site. Evaluation of the site during this inspection revealed facility equipment still in place as well as remaining chemicals (both new and in use at time of shut down) and substantial amounts of raw materials (e.g., cullet, dolomite). Many raw materials are stored in areas from which mobilization in storm water runoff is likely, the presence of solids on roadways and other areas around the plant appears to confirm such mobilization, and evidence of accumulated solids is apparent in the outfall channel below outfalls SW1 and SW2.

The division's current understanding is that this plant will not reopen as an AGC Glass facility. According to information communicated to the division during the inspection, sale of the site is anticipated within the next few months. Existing facility NPDES permit TN0003905 expires November 30, 2013, and reapplication no later than 180 days prior to expiration is required by

Compliance Evaluation Inspection AGC Flat Glass North America, Inc. - Kingsport Plant April 10, 2013 Page 2

permit Part II A.1. Possible transference of the existing facility NPDES permit was discussed, as was the possibility of NPDES permit TN0003905 termination and application for industrial storm water discharge permit (TMSP) coverage if necessary. As a reminder, compliance with NPDES permit TN0003905 provisions must be maintained until the permit is transferred or terminated.

Permit compliance helps ensure discharges that are protective of downstream fish and aquatic life and water quality. The division requests that you provide an update of facility status within 30 days of receipt of this correspondence. This update should also discuss the steps taken to ensure continued compliance with permit requirements. Thank you for your efforts to ensure permit compliance and to protect state water quality. If I may be of assistance in matters concerning this report, please contact me at (423) 854-5456.

Sincerely,

Bryan B. Carter Environmental Protection Specialist Division of Water Resources Johnson City Environmental Field Office

BBC/150313093

Enclosure

cc: Mr. Jeff Horton, DWR, Johnson City EFO

DWR Compliance and Enforcement Section, Nashville

File Copy, DWR, Johnson City EFO



United States Environmental Protection Agency Washington, D. C. 20460

Water Compliance Inspection Report					
	Section A: National Data Coding				
Transaction Code NPDI	ES yr/mo/dy	Inspection Type	n Insped	ctor FacType	
1 N 2 5 3 T N 0 0	0 3 9 0 5 11 12 1 3 0 3 2 Remarks	8 17 18	C	19 S 20 2	
21				66	
	lonitoring Evaluation BI QA Rating	LULULUULUNNNNNNNN	Reser	ved	
67 3 5 69	70 2 71 N 72 N	73 7	74 75	80	
	Section B: Facility Data	a			
Name and Location of Facility Inspected (Inspected (Ins	For industrial users discharging to POTW, also include	de Entry Time	: / Date	Permit Effective Date	
AGC Flat Glass North America, Inc. – Kingsport Plant		08:35 / 1	3/03/28	10/11/01	
1450 Lincoln Street, Kingsport, S Sanitary WW to Kingsport WWTP		Exit Time /		Permit Expiration Date	
Name(s) of On-Site Representative(s)/Title(s)/Phone and Fax Number(s)			3/03/28	13/11/30	
Victoria S. Conley / Corporate Environmental			Other Facility Data (e.g., SIC NAICS, and other descriptive information) SIC 3211		
Manager / (913) 787-2107 / (913) 592-6110 Victoria.Conley@us.agc.com			'uivinen & An	idrow Dullon	
Name, Address of Responsible Official/Title/Phone and Fax Number			Darrell Kuivinen & Andrew Pullen on site to ship finished glass.		
Bruce Flaherty / Regional Operations Manager			If necessary, continued sampling of SW		
			outfalls will be performed by Mike		
			r.	•	
Bruce.Flaherty@us.agc.com	☐ Yes 🖾	No			
	C: Areas Evaluated During Inspection (Check	only those areas e	valuated)		
Permit		eatment Program	<u> </u>		
Records / Reports	Compliance Schedule Pollu	tion Prevention			
Facility Site Review	☐ Laboratory ☐ ☐ Storm	boratory Storm Water			
Effluent / Receiving Waters	Operation & Maintenance Coml	peration & Maintenance Combined Sewer Overflow			
Flow Measurement		tary Sewer Overflow			
Section D: Summary of Findings/Comments (Attach additional sheets of narrative and checklists, including Single Event Violation codes, as necessary)					
SEV Codes SEV	Description				
	**				
			_		
			-		
Name (s) and Signature(s) of Inspector(s)	Agency/Office/Phone and Fax N		Date		
	1	Tennessee Division of Water Resources			
David D. Contac		TDEC DWR / JCEFO / (423) 854-5456			
Bryan B. Carter		(423) 854-5401 (FAX)			
	TDEC DWR / JCEFO / (423)				
Tine A Debines	(423) 854-5401 (FA)	^)			
Tina A. Robinson Signature of Management Q A Reviewer	Agency/Office/Phone and Fax N	Numbers	Date		
or management & A Neviewer	Tennessee Division of Water F				
	TDEC DWR / JCEFO / (423)	854-5447			
leffrey K. Horton	(400) 054	1 E A O A /E A Y \	1		



United States Environmental Protection Agency Washington, D. C. 20460

Water Compliance Inspection Report (Continued)

Section D: Summary of Findings / Comments

I. Permit (Satisfactory)

Permit conditions appear representative of past facility operations. Facility production operations ceased in November 2012.

II. Records/Reports (Unsatisfactory)

Facility is missing some storm water records required by permit Part IV, including some monthly equipment inspections, annual comprehensive site compliance evaluations, and employee training. No storm water records older than 2010 were present with the storm water pollution prevention plan (SWPPP).

III. Facility Site Review (Unsatisfactory)

Onsite equipment, chemicals, and substantial amounts of raw materials were largely left in place at time of shut down in November 2012. Facility assets are currently frozen pending sale. Only one or two employees are onsite and are involved in shipping finished rolled solar glass.

IV. Effluent/Receiving waters (Satisfactory)

No discharge was apparent from any facility outfall at the time of inspection. Outfall 001 was observed at monitoring manhole because the actual outfall point is not accessible from the facility.

V. Flow Measurement (Satisfactory)

No discharge was apparent from any facility outfall at the time of inspection.

VI. Self-Monitoring Program (Satisfactory)

Facility is currently shut down. No discharge apparent from any facility outfall at the time of inspection.

VII. Compliance Schedule (Not Applicable)

VIII. Laboratory (Unsatisfactory)

Available laboratory records for onsite analyses indicate use of methods no longer approved for use in Title 40 CFR Part 136. However, facility has been reporting No Discharge from outfall 001 since December 2012 because of shut down. Thus, no effluent analyses have been necessary.

IX. Operation & Maintenance (Satisfactory)				
Facility operations ceased in November 2012.				
X. Sludge Handling (Not Evaluated)				
XI. Pretreatment Program (Not Evaluated)				
XII. Pollution Prevention (Unsatisfactory)				
Substantial amounts of raw materials such as cullet and dolomite are present in outdoor areas exposed to storm water runoff. Material handling and storage procedures and site housekeeping efforts, required by NPDES permit Part IV, do not appear to have been successful at controlling solids migration.				
XIII. Storm Water (Unsatisfactory)				
There is visual evidence of solids leaving the site in the outfall channel below storm water outfalls SW1 and SW2.				
XIV Combined Sewer Overflow (Not Applicable)				
XV. Sanitary Sewer Overflow (Not Evaluated)				
XVI. MS4 (Not Evaluated)				
·				